

2nd. On the plating during the process of riveting
3rd. When the beams were in and fastened,)

in 1883 July 25 Aug 9 21 28 Sept 12 19

OK

REPORT, No. *5465*

FROM

Aull

DATE *27/3/18*

ON THE

Elsy

REMARKS OF THE CHIEF SURVEYOR.

*It is submitted that this vessel appears
eligible to be classed G.O.A. 1. as recommended
15th (iron)*



© 2020

Lloyd's Register
Foundation

HUL396-0278