

8991

REPORT of SURVEY for REPAIRS.

Change of Property

No. 582 Survey held at London Date August 6 1842
 on the Barge Spartan Master _____
 Tonnage 269 Built at Greenock When built 1839
 By whom built _____ Owners Thomson & Co
 Port belonging to London Destined Voyage West India
 If Surveyed ~~by~~ in Dry Dock Mr King

Original Survey, No. 746 Dated _____ Classed S.A. 1

Port Glyde, London 7816

REPAIRS

*At the present time
 Laid a new windlass. Repaired the
 Rudder of Head - & overhauled the Copper*

Present Condition of the

Decks <u>Good</u>	Transoms <u>not run</u>	Windlass <u>New</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>"</u>	Capstan <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Pumps <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>Reefed</u>
Waterways <u>"</u>	Plank & Treennails (Outside to the Water's Edge) <u>"</u>	Cables <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Breasthooks <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion.

*The vessel is in a very good & sufficient state
 in my opinion. Should remain as classed*

The Amount of Fee.....£ 1 : - : - is received by me,

Committee's Minute 19th August 1842

Character assigned S.A. 1

Wm. Clark
 Lloyd's Register
 Foundation