

REPORT of SURVEY for REPAIRS.

No. 20 Survey held at London Date 18th Nov 1854
on the Ship "Hallyards" Master Wright
Tonnage 299 Built at Port Glasgow When built 1818
By whom built John Wood & Co. Owners Campbell
Port belonging to Glasgow Destined Voyage Demerara
If Surveyed Afloat or in Dry Dock Young & Sons dry dock

Last Survey, No. 857 Port Glasgow Classed * A 1 S.S. 52
Rest 38-6 1/2 C-2

REPAIRS Now done, Yellow metal sheathing stripped off, and renewed on patent felt; and the bottom caulked from keel to Copper line - Rudder renewed.

Our attention having been attracted to the state of this vessel's topsides and wales, we made a verbal application to the Captain to have them scraped for our farther inspection; a request which has been complied with - On a more particular examination we were obliged to send a notice card recommending that "the defective and badly shifted planks in topsides and Wales be renewed before the vessel is recommended to the Committee for classification on her present character" -

signed { R.A.
B.W.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good where seen</u>	Timbers of the Frame <u>Good where seen</u>	Masts, Yards, &c. <u>Good and sufficient</u>
Lower Deck Beams & Fastenings <u>See</u>	Keelsons <u>See</u>	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides <u>Defective & badly shifted</u>	Rudder	Hawsers and Warps
Wales <u>Defective in place</u>	Copper <u>Yellow metal on felt</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>Good where seen</u>	When put on <u>now</u>	

General Observations and Opinion, As we do not consider this vessel eligible to be classed on the Asterisk character, while we think her capable of carrying, safely, dry and perishable cargoes, we recommend that she be classed A 1.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0
for attendance
Certificate (if required) : :

Committee's Minute 21st November 1854

Character assigned A 1 omitting asterisk

Notice to owner
on 21st Nov.



© 2019

Lloyd's Register Foundation

LOV 635-0271