

REPORT of SURVEY for REPAIRS.

27915-
NOV 29 1866

No. in Reg. Book. **No.** Survey held at London Date November 29th 1866
 on the "H. Falcon" p Glasgow Master John Mowden
 Tonnage 512 Built at Amsterdam When built 1845 1837
 By whom built _____ Owners James & John Foster & Deane
 Port belonging to Portsmouth Destined Voyage to Bournemouth and Southampton
 If Surveyed Afloat or in Dry Dock King & Queen Dock & East India Dock.

Last Survey, No. 1187 Port Southampton Classed 7th A. 1.
 REPAIRS now done. Rest 64 - 4 1.64

The yellow-metal sheathing stripped, and one plank in bottom on Port side renewed with American elm; re-caulked from keel to metal-line (deck also re-caulked), and re-sheathed with yellow metal over felt.

One Bower Anchor deficient.

Certificate of test produced signed by A. Sack, of the Lloyd's Cambrian Machine - for One Anchor - weight 20.2.23 ex-stock - proof strain 21.8 -
 14.12.66

Present Condition of the.					
Decks	<u>Recal Red & Good</u>	Treenails	<u>Good where seen</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Condition, how ascertained	<u>by inquiry</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>Sufficient</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of	<u>2.1.2.</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>do</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>do</u>
Plank (Bottom) and Counter	<u>"</u>	Copper <u>F.Y.M.</u> When put on	<u>Now</u>	Standing & Running Rigging	<u>do</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>Good where tested</u>	

The appears to be in good condition, and eligible, in our opinion, to remain classed A.

The Amount of Fee.....£ 1 : 0 : 0 is received by me
 Special..... 1 : 1 : 0
 Certificate (if required) : 5 : 0

Committee's Minute 30th November 1866
 Character assigned Rest 7 1/2 - (omit fee)
To have fig 6/12 Letter to Bureau 1/12/66
28/12/66

Register returned
20 Dec 1866
1866



© 2019

Lloyd's Register
Foundation