

Dixon & Co. h. 3/4 round


S. S. Ruskin

N. H. Report No. 8037

Intro

79

MDB739/223



OF BOILER BACK AS WELL AS ON INSIDE OF FIRE BOX.
STAYS 1/8" DIA AT BOTTOM OF THREAD TO HAVE UNITS ON OUTSIDE

MDB739/223



© 2019

Lloyd's Register
Foundation