

Advice notes for
Blair ref^{no} 1049 bills

S. S. Sledmere

Richardson duck ref^{no}

no 382 S.S.

Intro Report W. 345

1079



© 2018

Lloyd's Register
Foundation

MSA/1A/145

Steel plates Boilers No. 1079

Wardale

Yest No.	Yms	Ex %	
1118 B	27.0	29.0	Shell plates
1118 A	27.3	25.0	
1118	27.6	27.0	
1097 F	27.1	27.0	
1097 E	26.7	29.0	
1097 D	26.8	26.0	
1106	29.5	25.0	
1097 C	27.4	26.0	
1133 B	26.7	25.0	Boiler ends
1133 E	27.0	31.0	
1118 E	28.3	25.0	
1118 F	27.8	23.0	
1100 B	28.5	25.0	
1117 B	28.5	25.0	
1118 D	27.3	23.0	
1118 C	27.8	28.0	
1117 A	28.4	28.0	
1117	29.1	27.0	
1117 E	28.5	27.0	Back Tube plates
1117 A	28.2	25.0	
1117 F	28.0	26.0	
1117 C	27.5	27.0	
1104 F	26.8	30.0	Flame Box Backs
1104 H	26.2	27.0	
1104 J	27.5	30.0	
1021 D	26.8	29.0	
1117 C	28.6	26.0	4 ff Furnace Bottoms
1117 J	28.9	27.0	8 ff Butt Straps
1117 D	28.4	28.0	8 ff
2882	26.6	25.0	Corrugated Flues
2883	26.4	25.0	
2884	26.9	26.0	
2885	25.8	24.0	



© 2018

Lloyd's Register
Foundation

Steel plates Boilers No. 1079

Test No. Tons Exp.

700BB 28.4 24.0 2 off Flame Box Sides and
Crowns

700AA 28.9 25.0 2 off

700WW 27.6 28.0 2 off

700MM 26.4 23.0 2 off

700LL 26.0 23.0 2 off

700VV 27.9 26.0 2 off

1001 28.8 25.0 18 off Roofing Stays

988A 27.4 23.0 20 off

988A 28.8 23.0 9 off

1001 28.8 25.0

1118 27.6 27.0 2 off Man Hole Rings and
Drops

1118A 27.3 25.0 2 off

Steel Stay Bars

9929 - 93 2 off

" 69 2 off

" 68 2 off

" 86

" 84

" 83

" 88

" 79

" 89

" 78 2 off

" 81

" 129 2 off

9929 - 77 2 off

" 85 2 off

" 87

" 82

" 90

" 132 2 off

" 133 2 off

" 131 2 off

" 128 2 off

" 91

" 130 2 off

" 80

17/12/90



© 2018

Lloyd's Register
Foundation