

Reference

M.

Lloyds Register of British  
and Foreign Shipping.  
Dock Office Buildings, West Hartlepool.

14<sup>th</sup> March 1889

The Secretary,  
Sir,

With reference to your favour of the 12<sup>th</sup>  
instant in re. the 1<sup>st</sup> entry report on Messrs. Rogers & Son,  
No. 232, - "Akaka" - It has now been amended and agreed  
with the vessel as built.

The brackets outside the flange plates of double-  
bottom have been extended up the bulges as required.

The strakes of the deck plating adjacent to the  
S. & B. openings have been increased as shown on the  
plan, but the plating adjacent to the fore hatch has  
not been increased. This hatch is only 16 feet long and  
it was considered that the paragraph in your letter of 13<sup>th</sup>  
July 1888, did not apply to openings of this size.

Current plates have been fitted (6.0 x 2.6) on the strong  
hold beams not only where the spacing exceeds 10 frame spaces  
but to every strong hold beam in the vessel.

I am, Sir,

Your obedient servant,

Allison B. Wilson.

STK919-0501

the reports and plans are returned herewith.



For the Chief Surveyor  
A8D

15/3/89



© 2021

Lloyd's Register  
Foundation