

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

23 JUN 1950

S NAME

PINHEL.

REPORT

Lis. No. 511.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

This vessel holds the notation of "Laid up pending survey" .

A General Examination held to enable the vessel to proceed in tow to a U.K. port in ballast, for breaking up purposes.

One of the boilers examined throughout and also pumping arrangements examined.

IT IS SUBMITTED ACTION be deferred pending confirmation of the breaking up of the vessel.



© 2020
22.6.50.

Lloyd's Register
Foundation