

COPY.

GRAMS: SURVEYOR, BALTIMORE



Lloyd's Register of Shipping

1223-24 Munsey Building

Baltimore-2, Md., U. S. A.

Reference S

7th September, 1948

The Secretary
London

Dear Sir:

We are in receipt of your air mail letter of the 31st ultimo having reference to the steamer "SEWALL'S POINT" and the repairs stated to have been effected at Laspezia.

As promised in their letter to this office, dated June 29th last, the Owners arranged for the vessel to visit Baltimore and informed us that it was in order for us to carry out the inspection of the repairs made at Laspezia.

These repairs were found to be general hull and machinery repairs and nothing had been done to the stern and poop deck or the collision damage starboard side. These outstanding items were examined by the undersigned who found no change in the condition since the previous examination.

The Owners' General Manager, who accompanied the undersigned during the inspection of the vessel, stated that at the termination of the present Charter in November next it is their intention to return the vessel to an Italian port where she will be submitted for Special Survey.


Our report on the case (Balt. Rpt. No. 8678) was forwarded to New York August 12th last.

Yours faithfully,

For the Surveyors

RL:S

PHONE: PLAZA 2411-2



Appendix to Register B

Panama

Voyage... Nova

Particulars of Classification (wh

Register Book & S

of (includ

11.47 HLM

7.44 MS

TS

not fitted

signed) as }
now verified }

inquiries of

to have been

er, copy of

plating no

the foredeck

in way of wa

was recommen

d not permit

er, or Y.M.
(State if on Feli.)
n fitted, Month

s, Yards, &c.

lition, how ascertained.
(State if wedges removed,
pment letter

aors, No. of

les (State if now ranged)

length
(on board)
Rule length

in Locker

users & Warps

ding and Running Rigging.

the Register Book consequ

as classed and to have re

ow classed, witho

ward side aft, and

Survey being carried

try in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

5M-3-48

PRINTED
IN
U.S.A.



© 2020

Lloyd's Register
Foundation

W1029-0099

Referred to Mr. Perris.

R2

RECEIVED
AUG 13 1901
A.M.

A. S. U. B. M. S. 2101111111


gubh8 y88888 11-11111

gubh8 y88888 11-11111



© 2020

Lloyd's Register
tion



210

Surveyed t
on account...

and that

Register of

recommende

that I has

entered with

book-keeping
forward in w
the Greel
end to the N
being fir Bo

Certificate is issued
the Committees of
it is to be understood
to be held responsible
ity in the Register Boo
its Committees or any