

COPY.

YDS REGISTER
LONDON.

OP 25 OCT 1917

182

Time of Receipt

10 33


TELEGRAM.

POST OFFICE



TELEGRAPHS.

Office Stamp.



ded in at

Office of Origin and Service Instructions

Words

Charges to pay

42 NEWCASTLEONTYNE T: 19=

THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM.

Received here at

COMMITTEE FEN LONDON: =

1021.4

M.

STEAMER SANGENNARO UPPER DECK PLATING HALF
NGTH AMIDSHIPS CLEAR OF BRIDGE POINT FOUR TWO
HICK: = REGISTER: ::



© 2021

Lloyd's Register
Foundation

W1048-0092

BEAMS, Upper Deck, single Angle, Bulb Angle,
Plate, Tee Bulb or Channel.....
Spacing
BEAMS, Second, Third & Fourth Deck, Single
Angle, Bulb Angle, Plate, Tee Bulb or Channel

9	3 1/2	50	9	3 1/2	50
9	3 1/2	50	9	3 1/2	50

Angles on ditto, No. 2
Tie Plates, outside Hatch
Deck. Material and thick

Referred to the Chief ~~St~~ Surveyor.

7711

OCT 25 1917

M
25.10.17



© 2021

Lloyd's Register
Foundation

STEAMER
DECK
CLEAR
FOUR