

-1 DEC 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME

MUINAM

Rpt.

Msl

No. 70214

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey.....

The class is subject to bronze liner on lower rudder pintle being dealt with at the next dry docking.

The MARSEILLES Surveyor reports the vessel placed in dry dock and the bottom and rudder examined.


The bottom rudder pintle, as above, skimmed up and bronze liner renewed.

The vessel has now been taken over by the German Authorities.

Further information could not be obtained.

The case is submitted for the consideration of the Committee as to whether the particulars of the vessel's class should be removed from the Register Book.

© 2020



Lloyd's Register  
Foundation

11658-0140