

Lloyd's Register of Shipping,

14, Castle Buildings,

Durban, South Africa,

EWART, M.I., MAR. E., LON.
SURVEYOR.

LLOYD'S REGISTER
Recd. 29 SEP. 1925

AREA: 5/10
LONDON

26th August 1925

Dear Sir,

S.S. "Alмасcos"

The Agent for this vessel advised me that she was going into dry dock and asked if it would be necessary to call a Survey. I replied that it was necessary to Survey vessels when in dry dock and handed him a written copy of the Society's Rules relating to annual Surveys. I heard nothing further and the vessel was dry docked but no Survey called. I phoned the Agent and he replied that the Master did not consider a Survey necessary; therefore no Survey was held.

I am, Dear Sir,
Yours faithfully,
John Stewart.

The Secretary
Lloyd's Register of Shipping.
London.

SURVEYOR TO LLOYD'S REGISTER.



© 2021

W1162-0056
Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor

29 SEP 1925

Also for Mr. S. A. Hill to note
Also for Mr. Maxine to note

As there is no survey required by
the rules due on this vessel & as the
surveyor at the port is a non-exclusive
surveyor, it is not seen that any action
can judiciously be taken.

It is worthy of consideration as to
whether non-exclusive surveyors, after
having offered their services & which have
not been taken advantage of, should not
in all such cases advise the office
so that it may be on record that the
Ship was in dry dock.

BH
1. 10. 25


BH

2501 2001 1925

British South Africa

14' Castle Buildings

inquire to register a vessel



© 2021

Lloyd's Register
Foundation

TELEPHONE NO. 433

LETTER NO. 128101 100525