

COPY

LLOYD'S REGISTER OF SHIPPING.

PORT Colombo.

21st April, 1943.

THIS IS TO CERTIFY that

I, H. NIGHTINGALE,  
 the undersigned Surveyor to this Society did at the request of  
 Messrs. Shaw Wallace & Co., Ship's Agents, attend at Walkers Shops  
 on February 25th. 1943 and subsequent dates, and on board the m.v.  
 "ATHELMONARCH" No.69763 in the Register on April 14th. 1943 and  
 subsequent dates in connection with the supply and fitting of a new  
 steam cylinder block for windlass and for completion of Annual  
 Boiler Survey.

WINDLASS Cylinder Block. This was seen by me at all stages, the  
 casting being found to be sound and the machining completed  
 in a workmanlike manner. On completion of fitting up on  
 board, the windlass was seen under working conditions, the  
 starboard anchor being lowered and raised twice, all being  
 found to be in order.

BOILER. The port boiler was surveyed internally and externally,  
 also all valves, cocks, mounting, boiler bearers and chocks  
 and found to be in good condition throughout. The safety  
 valves were again adjusted to the allowable pressure of  
 180 lbs per square inch, the thickness of the compression  
 rings being - Forward 11/32" Aft 5/16".

Survey Fee :- Windlass ...Rs.180/-  
 Boiler ...Rs. 90/-  
 Trav. Exps. (6 visits) ...Rs. 24/-  
 Rs.294/-

Surveyor to Lloyd's Register.



Lloyd's Register  
 W1776-0065  
 Foundation