

Im,3.43.

28 JUL 1943

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "DEVIS" REPORT Mch No. 11513

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented shell plating etc. (s.s.) in way of No2.hold and indented shell plates F.7, G.8 & 9 (s.s.a.) and frames in way and C.6 (p.s.f.) being dealt with at the Owners' convenience.

The MANCHESTER Surveyors report the vessel afloat and repairs effected to a fractured shell and fractured bulkhead plate. Additional accommodation fitted in Nos.4,5 & 6 Upper 'tween Decks.

IT IS SUBMITTED the vessel is eligible to remain as classed, subject as above.

As now, subject.



W1187-0135