

F.E.
(FBD.)

5c.12.36.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"POZARICA"

Rpt.

Sld.

No.

32275

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 7273

Depth "d"

15.44

2nd Long. No. 20256

Proportions = $\frac{L}{D}$

11.33

Framing Bulb angle frames as approved Sheerstrake

As approved
(plus Owners'
increase)

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "With Freeboard"

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk. and Shelter Dk.

Cell.DB 228' 476t, FPT 30t, APT 57t.

(Coll.BH to Shelter)Dk., 4BH to 2nd Dk.)

FK, 5BH. / pt.cem., Lloyd's A & CP.

B 87'

O.L. 306' -7"



© 2021

18.1.38

Lloyd's Register
Foundation

W1192-0036

thickness of Intercoastal Plate...

Spacing.....