

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Vessel No. 99612 Port Liverpool)

SHIP FORGINGS ~~OR CASTINGS.~~

I have to report that the undermentioned Iron ~~or Steel~~ Forgings ~~or Castings~~, manufactured by Messrs J. S. Foster & Sons Ltd. of Sunderland for the Vessel No. 518, being built by Messrs Crickton & Co. Ltd of Chuter have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Forgings ~~Castings~~

Lloyd's
No. 6310
7.31.J.D

J. Dickie
Sunderland


	STERN FRAME.	RUDDER FRAME.	Quadrant & Hand STEW. Liller
...	/	<u>P. M. Eng't Steel</u>	<u>Scrap Iron</u>
...		<u>Roller Bar</u>	<u>Forged</u>
...		<u>3/4 by 2 3/4</u>	
...		<u>Forging & Machining</u>	
...		<u>22.7.31 to 30.7.31</u>	
Inspection ...			
Inspected			
STINGS.			
Standard Test pieces.			
Test—			
square inch		<u>Rudder-arms</u>	
per cent. ...		<u>Forged from</u>	
ing Test—		<u>Scrap Iron.</u>	
re fracture			
ground ...			
Test—			
ording to Rules			
d satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(any chargeable) £

be paid at

on, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



© 2020

Lloyd's Register Foundation

W12SS E0081

For the information of Surveyors and the Committee only

Lloyd's Register of Shipping

London

SHIP FORGINGS

Handwritten notes and signatures in the left margin, including 'The ... for the Eng ...' and 'ave been e seen, s ...'.

Forging reports

E.S. MARIA

LIVERPOOL

Report No. *99612*

Handwritten notes and signatures in the center of the page, including 'BUDDER BEAVE' and 'L. ...'.



© 2020

Lloyd's Register Foundation

Other tanks, if fitted, (If necessary, furnish further information by sketch.)

Total capacity of double bottom

* The wells are not to be included in the lengths of the tanks.