

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 35983 Survey held at on the Wood, Iron or Steel Date, First Survey Taito Maru Last Survey 19

TONNAGE - 2427 Built at Aichi Harima By whom Harima Dyk. Co. Ltd. When 1917 9
GROSS 2372 Owners Taito Kisen Goshi Kaisha Owners' Address (if not already recorded in Appendix to Register Book).
UNDER DK. 1896 Managers Port belonging to Hashidate
NET 1896

Surveyed Afloat or in Dry Dock? W=B=CellDBorDBa Name of Dock feet; uE&B feet; f feet Destined Voyage Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Year Assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A1 2,33		* LMC 2,33
ss Hole No 3-3,30		TS 2,32

Last Report, No. 8082 Port Kof

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE			
Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Cables (State if now ranged)
Frames	Have Pumps now been examined and found efficient?	Planking of Wood Vessels	" length mean diam. (on board)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" Rule length size
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stimson ditto	Standing and Running Rigging
Floors		Transoms, Pointers, & Crutches ditto	
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute ERI. 23 MAR 1934
Character Assigned Withdraw Class
Decision of Classing Committee confirmed hob
Surveyor to Lloyd's Register of Shipping. General Committee
Thursday, 5th April, 1934
Lloyd's Register of Shipping
W1265-0136

If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so, to be sent to