

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. 86571 Survey held at on the Wood, Iron or Steel "Tosna" Karaya Date, First Survey Last Survey 19... (No. of Visits)

TONNAGE: Built at Grangemouth By whom Grangemouth Dryd Co. Ltd When 1922 YEAR. MONTH. 8
GROSS 1955 Owners Scottish Owners' Address
UNDER DK. 1744 Managers Port belonging to Leningrad
NET 1188

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 89686 Port NWC

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned to expiry	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100 A1 1,33</u>		<u>L10 3,30</u>
<u>n Gls No 2-30</u>		<u>BS 1,33</u>
		<u>CL 1,33</u>

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	State if Tanks have been examined inside
Caulking of Decks	State if Tanks now tested
Coamings	Bulkheads
Beams & Fastenings	Ceiling
Outside Plating	Cement or Asphalt (State which.)
" " in way of sidelights	Rudder
Breasthooks	Steering gear and its connections
Transoms	Windlass
Frames	Have pumps now been examined and found efficient?
Reverse Frames	
Longitudinals	Have Sluice Valves now been examined and found efficient?
Transverses	
Floors	Have Watertight Doors now been examined and found efficient?
Keelsons	
Stringers	Have Ventilators and their Coamings been examined and found efficient?
Inner Bottom Plating	
Air and Sounding Pipes	
Dbng. Plates under Sounding Pipes	
Engine Room Skylights	
Coal Bunkers, Open'gs, Lids, &c.	
Oil Bunkers	
Scuppers	
Cargo Hatchways	
Hatches	
Planking of Wood Vessels	
Caulking ditto	
Treenails ditto	
Breasthooks & Stems ditto	
Transoms Pointers, & Crutches ditto	
Timbers of Frame at openings ditto	
Ditto Ditto at other places ditto	
Stringers, Clamps & Shelves ditto	
Salting ditto (State if examined.)	
Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year	
Boats	
Masts, Yards, &c.	
Condition, how ascertained (State if wedges removed)	
Sails	
Equipment letter	
Anchors, No. of	
Chain Locker	
Cables (State if now ranged)	
" length (on board) mean diamr.	
" Rule length size	
Hawser & Warps	
Standing and Running Rigging	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	19
Travelling Expenses (if chargeable)	£	:	Received by me,
Second Surveyor's Fee (if any)	£	:	19

Committee's Minute TUE. 2 OCT 1934
Character Assigned withdrawn class
written down
do. 1/10

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 4th October, 1934
Decision of Classing
Committee confirmed
Lloyd's Register
Foundation
W1272-0038

The Surveyors are requested not to write on or below the space for Committee's Minute.

Is Certificate required? If so, to be sent to