

Received from Chief Surveyors

M. Se: "SAN UGON"

Report

Mob

No. 979


For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Collision & grounding

When due

Subject to a bower anchor being supplied at first convenient opportunity.



© 2021
Lloyd's Register
Foundation

W1303-0075