

nt to Chief Surveyors.

Received from Chief Surveyors

VESSEL'S NAME *Mt. Tw. Sc. PRABHAVATI*

Report

*L/S*

No.

*53862***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

*First Entry*

When due

✓

✠ A. 1 (Steel) "With Freeboard" "For Coasting Service  
Bombay & Goa"

*1 Dk**Cell DB v. E 18' 37t, FPT 14t, APT 23t.**FK, 8BH, ~~ft~~ ft up, Lloyds A & C.P.**Shade Dk.*

© 2021

Lloyd's Register  
Foundation*5.10.23*  
*W1317-0118*