


FREEBOARD REPORT on the

"HARPAQUS"


It is submitted the Barry Surveyors be requested to state the number of tarpaulins to the hatchways on the freeboard deck, the hatchways on the superstructure decks and the hatchways in the Bridge deck. They should also report the condition of the exposed ventilations the Forecastle and Poof decks ventilating the spaces below.

J.S.



29.5.37

dr. 31/5



© 2021

Lloyd's Register

Foundation

W1018-0189