


Rudder
Trunk

CRACK
PORT SIDE

STEEL PLATING

18 FE



SAND HOLES
STBD. SIDE

17 FE

Rudder
Post



© 2021

Lloyd's Register
Foundation

W1352-0111