

1

Sent to Chief Surveyors 7-6-21

Received from Chief Surveyors _____

VESSEL'S NAME Steel of "MIDDLEBURY" Report Gal No. 1079

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~


(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Docking When due _____

Subject

Steel watertight covers to be fitted to small cattle hatches on the main deck at the earliest opportunity.

M
ASB
8-6-21



© 2021

Lloyd's Register Foundation