

Less Engine Room 1528.92
Less Navigation Spaces 88.82

Register

Upper Deck at side
to top of keel

Port belonging to Gloucester
and

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 1363 } RECTOR
{ 1364 }

ONE LOMBARD 35

LLOYD'S REGISTER OF SHIPPING,

LLOYD'S REGISTER, 17 BATTERY PLACE
LONDON.

REC'D 24 MAR 1919

NEW YORK March 10, 1919.

ANS'D

Disch
Inclosed HH

Dear Mr. Scott:

With reference to your letter of the 12th ultimo and to Philadelphia report No. 3060 on the steamer "INDIANAPOLIS" I enclose herewith a letter dated the 8th instant received from the Surveyors from which it will be seen that the thickness of the floors are 17.1 lbs. and 21.22 lbs. in the boiler room and the spacing of same being 6' - 0". The rivets in longitudinals 10, 11 and 12 from Shelter Deck are spaced four diameters on each side of the bulkheads,

Yours faithfully,

R P Hutchinson

A. Scott, Esq.,

LONDON.



© 2021

Lloyd's Register
Foundation

W1474-0153

W1474-0154

Fee Bulb or Unanner
Angles on upper edge

.. The Plates
.. Deck, Material and thickness

Steel

For Mr Mayne

a.s.

24/3/19

M
17 4 19

Engine Room	814.81
Tonnage for Fees...	1528.92
Less Engine Room	88.72
Less Navigation Spaces	
Register	

© 2021

Lloyd's Register
Foundation



The

Dear

Repor

that

Boil

the

are

Lee Build or Channel
Angles on upper edge
Spacing