

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

77 MAY 1942

VESSEL'S NAME ARDENVOHR Rpt. Brs. No. 15079**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

(" The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The class is subject to cargo battens being fitted in Nos.3 & 5 holds and part of No.1 hold at the first opportunity and to (a bower anchor and 45 fathoms of chain cable being supplied).

The BRISTOL Surveyors report the vessel placed in dry dock, bottom coated, and decks, casings examined and found in order.

The items, as above, have not been dealt with.

It is submitted the vessel appears worthy to remain as classed with record of docking survey 4.42, subject as above.

100A1)
With freeboard) Subject etc.
2.42 Brs.)



© 2020

BPM
8-5/42
Lloyd's Register
Foundation

W161-0130