

5th November, 1940.

My Dear Cyril,

With regard to Glasgow First Entry Report 62950 on the motor ship "ARDENVOHR", it is presumed that the "Subject" in your Minute referred to the fitting of cargo battens in Nos. 3 and 5 holds and part of No. 1 hold and not, of course, to the equipment which simply appears as a stamp on the First Entry Certificate.

It is noted that the remainder of the cargo battens are to be fitted on the vessel's arrival in the United States and I shall be glad to learn what you want us to do regarding the issue of a certificate. Should we issue a half Certificate at once and delay the issue of a full Certificate until the cargo battens have been placed in order or would the Builders prefer to have a full Certificate now with the "Subject" added.

With kindest regards,

Yours sincerely,

C.R. Willis Esq.,

GLASGOW.



© 2020

Lloyd's Register  
Foundation

W161-0136