

THROUGH HELSINGFORS  
COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen. London

Telephone: ROYal 3551 (6 Lines)

8th July, 1953.

Classn(S)

Dear Sirs,

Steamer "WASA"

GFA

A report has been received of the survey which was recently held on this ship by the Society's Surveyors at Amsterdam, from which it is noted further temporary repairs were effected to the ship's side end of the starboard ash shoot, which was found to be corroded.

It is recommended that the end of the ash shoot should be renewed before the end of May next, and the vessel's class has been continued subject to this matter receiving attention by that time.

I would take this opportunity to remind you that the vessel's class is also subject to 45 fathoms of chain cable being supplied at the earliest opportunity, and to the main engine back columns being further examined before the end of October, 1954.

Yours faithfully,

c.c.Hfs.

Assistant Clerk to the  
Classification Committee.

Messrs. Henry Nielsen A/B, O/Y.,  
Fabiansg 6,  
P.O.Box 88,  
HELSINGFORS,  
Finland.



© 2020

Lloyd's Register  
Foundation

W164-0008