

COPY.

GLASGOW REPORT No. 66765

Lloyd's Register of Shipping.



Port GLASGOW

8th March, 1943.

This is to Certify that I have

Surveyed the ~~Boiler~~ and Machinery of the M.S. "EMPIRE ROWAN"
9545 gross tons of London

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have Recommended that the record of L.M.C. C.S. with date

be made in the Register Book in the case of this vessel when the survey has been completed.

Parts now examined:—

STARBOARD ENGINE

No. 4 main cylinder, cover, liner, piston, top and bottom end pins with bearings, valves, valve gearing and all main and compressor crankshaft journals and main bearings also intermediate shafting examined and found or placed in good order.

PORT ENGINE

covers

No. 4 and 7 main cylinder, liners pistons, top and bottom end pins with bearings, valves and valve gearing examined and found or placed in good condition.

AUXILIARY ENGINE

No. 3 Port dynamo engine examined in its entirety. Lower starboard forward air starting reservoir and the port forward and aft lubricating oil pumps examined and found in good order.

W. Dawson.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."