

COPY.

Lloyd's Register of Shipping.



Port Hong Kong

5th. March 1938.

This is to Certify *that I have*

Surveyed the Boiler ^{Part} and Machinery ~~of the~~ and Propeller Shafts
of the Twin S.S. "EMPRESS OF CANADA" of London, 21517 Gross
Tons, No.24415 in the Register Book.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended *that the record of* B.S.3-38., M.S.3-38. and
Tail Shafts seen C.L. 2-38.

be made in the Register Book in the case of this vessel.

J. H. Morrison

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."