

112 JAN 1937

"THODE FAGELUND"

N.Yk. 37220

inchy

The 2nd S.S.No.1 became due 9,36.

The vessel was last examined in dry dock 6,36.

The Special Survey has now been commenced (vessel afloat) by the examination of the steering engine.

The fidley top found somewhat corroded and a considerable part will require to be renewed, but it is stated to be safe for a year.

The survey was confined to the above.

It was stated the Survey would prob^aably be carried out when and if the vessel was reboilered.

When the case received the consideration of the American Committee on the 23rd ultimo action was deferred.

It is submitted the Owners be written to with a view to ascertaining their definite intentions respecting the completion of the Survey and informed that a reasonable portion of the Survey should be carried out at the earliest practicable date or a General Examination made so as to permit of the vessel's general condition being ascertained if it is intended to take advantage of the year of grace.

Mr.Bennett of the New York Office should be informed of the Committee's practice regarding cases where it is desired to take advantage of the year of grace.

Ytd
12.1.37

*See also attached enclosures
on Report 8.*



© 2020

Lloyd's Register
Foundation

R. J. S.

By submit to your
Committee



© 2020

Lloyd's Register
Foundation