

4 JAN 1945

"DUMFRIES"

L.A. 10057.


The class is subject to the cast iron bilge pump chamber and general service pump discharge valve chest being examined before the end of 12.44 and renewed at first opportunity.

Other Repairs effected to General service and ballast pumps.

It is submitted that this vessel is eligible to remain as classed subject as above.

Kell

3.1.45



© 2020

Lloyd's Register
Foundation

W240-0002