

8A

20 AUG 1941

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

Draco

Rpt.

Alx

No. 2123

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

re of Survey

DAMAGE. 7 wastage

The *Alexandria* Surveyors report this vessel examined afloat on account of damage through collision

Shell plate No 5, 2nd strake below sheer (S.S) found indented

Temporary repairs have been effected to their satisfaction, and the Surveyors recommends this plate be dealt with at Owners convenience. (1)

Temporary repairs also effected to washed deck plating in tween deck bunker (p.s) & the Surveyors recommends permanent repairs at Owners convenience. (2)

It is submitted the vessel is eligible to remain as classed without record of survey, subject as recommended. (1) + (2)

20.8.41

as now, subject, etc.



© 2021

Lloyd's Register Foundation

W26-0200