

TELEGRAMS
"CORRUGATED
MOTHERWELL"

SPECIALTY:—CORRUGATED FURNACES

TELEPHONE
MOTHERWELL 900

20 JAN 1944

THE BROOMSIDE BOILER WORKS COY LTD

CAMP ROAD.

MOTHERWELL,
LANARKSHIRE.

17th. January. 19 44

To The Mercantile Dry Dock Co., Ltd.,
JARROW.

Ref Ordered by The Wallsend Slipway & Eng. Co. ex. The Boiler
Boiler No. Furnace Co. Ltd. Our Job No. 1760.

S.S. "CSIKOS"

No.	SECTION.	Length	Internal Diameter	Thickness
4	"DEIGHTON" with SADDLE FLANGED BACK ENDS. (BACK AND FRONT ENDS TO TEMPLATES)	7' 1" (Approx)	3' 1"	1/2"

Plates by Colvilles Ltd.,

Nos 2/4588, 2/4590. *One of each fitted to Stack Boiler*

The Plates have been subjected to mechanical tests and the furnaces passed for workmanship and found satisfactory by Surveyor.



W268-0117