

EMM.

1830

~~7879~~

APPLEBY IRON COMPANY, LTD., SCUNTHORPE,

LINCS.

Customer Paul & McLeod, Glasgow.Date 29/1/30.Builder Messrs. D. & W. Henderson & Co. Ltd.,

Mark or Job No.

Boiler. TENSILE—Tons per sq. inch 26/30Batch No. 13/19Customer's Order No. A. 263

REQUIREMENTS ELONGATION—per cent.


Inspection Lloyds.Works Order No. 5624 J. 259CONTRACTION OF AREA—per cent.
ELASTIC LIMIT—
per sq. inch or per cent.

We hereby certify that the material described below has been made by the Open Hearth process, and is that which has been satisfactorily tested
in the presence of the Surveyor, in accordance with the rules of Lloyd's Register.

901

Initials of Test House Manager.....

PLATE No.	CAST MARK	POSITION	TEST RESULTS	PLATE MARK	PIECES CUT	SIZE	THICK- NESS	APPROX. WEIGHT T. c. qr. lbs.	REMARKS.
<u>Q. 686</u>	<u>6771</u>			<u>W.W.</u>	<u>1</u>	<u>To Skt.</u>	<u>13/16"</u> <u>5/8"</u>	<u>14 3 13</u>	
<u>724</u>	<u>"</u>			<u>"</u>	<u>1</u>	<u>" "</u>	<u>"</u>	<u>14 3 13</u>	



© 2020

Lloyd's Register
Foundation

W3-0096