

EMM.

1909
~~XXXXXX~~
7682APPLEBY IRON COMPANY, LTD., SCUNTHORPE,
LINGS.Customer Paul & McLeod, Glasgow. Date 28/1/30.Builder Messrs. D. & W. Henderson & Co. Ltd.,

Mark or Job No.

Boiler.

TENSILE—Tons per sq. inch 28/32Batch No. 2/16Customer's Order No. A.263

REQUIREMENTS

ELONGATION—per cent.....

Inspection Lloyd's.Works Order No. 5624 J. 259


CONTRACTION OF AREA—per cent.....

ELASTIC LIMIT—
per sq. inch or per cent.....

We hereby certify that the material described below has been made by the Open Hearth process, and is that which has been satisfactorily tested in the presence of the Surveyor, in accordance with the rules of Lloyd's Register.

Initials of Test House Manager.....

PLATE No.	CAST MARK	POSITION	TEST RESULTS	PLATE MARK	PIECES CUT	SIZE	THICKNESS	APPROX. WEIGHT				REMARKS.
								T.	c.	qr.	lbs.	
B. 458	6752			901 M. 1 B.	4	9'1" x 18 $\frac{1}{4}$ "	1"	1	0	0	12	S.
A+B 544	6768			S.	1	21'4 $\frac{3}{4}$ " x 120 $\frac{1}{2}$ "	1 $\frac{1}{8}$ "	4	8	0	2	
A+B 545	"			S.	1	" "	"	4	8	0	2	
559	6753			O.B.	2	10'0 $\frac{1}{2}$ " x 18 $\frac{1}{4}$ "	$\frac{7}{8}$ "	9	2	26		S.



© 2020

Lloyd's Register
Foundation

W3-0099