

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 0220
0221
0222
0223 } WHITEHALL-4

Lloyd's Register of Shipping,

17 Battery Place,

New York.

December 9, 1940



Please address further communications on this subject to THE PRINCIPAL SURVEYOR

Dear Sir:

S. I duly received your letter of the 25th October last having reference to New York Report No. 40285 of Partial Classification Survey on the Steamer "WEST CAWTHON", renamed "EMPIRE BISON", and in reply I may say that the Surveyors confirm that the scantlings of the frames, beams, stiffeners, etc. were verified generally with those shown on the plans; the thicknesses of the shell, deck and bulkhead plating were checked on edges but plating was not drilled at this time.

There were insufficient marks on the anchors and cables to permit of their being identified and the particulars of stream wire, towline, hawsers and warps were not obtainable on the occasion of this survey.

I am, Dear Sir,

Yours faithfully,

Principal Surveyor
U.S.A. & Canada

The Secretary

WOKINGHAM



© 2020

Lloyd's Register
Foundation

W30-0124

1 FEB 1941

H

[Handwritten signature]

[Handwritten signature]

March 31/12



© 2020

Lloyd's Register
Foundation