

AME

1000015

Report

No.

ESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in $20 \frac{140}{100}$ of an inch.

	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
10	13	(doubtful)	10 1/2			13	14	14 1/2			13	17	17			(a) Adjacent plate drilled
N	16	12	13			11	12	13			11	12	13			12 13
KE 11	14	11	14			15	10 1/2	10 1/2			12	7 1/2	8			12 13/20
L	14	10 1/2	11			11	8 1/2	8 1/2			12	8	8 1/2			(b) Patched plate. To be
K	14	13 1/2	14			11	7	7 1/2			12	11	9			renewed. Plate forward
J	14	12	13			11	10	9 1/2			14	9	9			drilled 1 1/2 x will be
H	16	14	15			11	10 1/2	10			16	14 1/2	14			renewed. Plate abaft
G	17	16	16			12	11	11			16	15	15			drilled 13.
F	16	12	15 1/2			12	9 1/2	9 1/2			16	Stealer				
E	14	13	14			11	Stealer				14	do				A number of additional
D	14	20	20			12	10 1/2	10			14	16	14			isolated drillings taken.
C	14	16	12			12	12 1/2	12 1/2			14	Stealer				
B	14	17	17			13	12 1/2	12 1/2			14	Stealer				

B 14 17 17

A 15 10 14

d. 20 33
doubtful 13/20

12 Stealer

14 14 14

15

12 Stealer

14 15 15

15

12 do

13 17

11

Lloyd's Register
Foundation
W309-0059