


Note. (per Mr. Young 27. 4. 42.)

S.S. Empire Explorer (ex "Inanda")

The Electrical Installation has been renewed
throughout except the 30 K.W. Dynamo Set. See
London Report No. 110267



© 2020

Lloyd's Register
Foundation

W32-0014