

Rpt. 14.

RETAIN

Port of Baltimore Md.

Sept. 24th 1942

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the U.S. Ocean

I have to report that I found standing rigging in satisfactory condition with the exception and recommendation as under noted.

All wire and parcelling removed from splices in lower ends of rigging and lower 1st stays wire cleaned off. Parcelling and wire to be renewed, and wire coated.

David B. Campbell

Fee \$20.00

To the Surveyors,
Lloyd's Register of Shipping,

Printed in U. S. A.



© 2020

Lloyd's Register
Foundation

W346-0088

W346-0081