

COPY.

# Lloyd's Register of Shipping.



Port LONDON,

15th August, 1940

This is to Certify that I have

Surveyed the steamer "ARABY" 4936 tons gross of Liverpool whilst vessel was lying afloat at Victoria Dock, London, on the 14th August, 1940, on account of damage stated to have been caused by collision with steamer "CELTIC STAR" at Freetown, West Africa, and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all temporary repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued as classed, viz. 100 A1 shelter deck with freeboard, subject to indented plates, sheerstrake No. 2 and strake above sheerstrake Nos. 2 & 3 (starboard side) being dealt with at Owners' convenience; also, to indented shell plating port and starboard, and gutter plate in hold (being dealt with) being fit to carry dry and perishable cargo.

*J. D. Perry*

Fee:- £3.3.0

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

