

500,940.

at to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME..... "DEMETERTON"..... Report..... Liv..... No..... 115746

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey..... When due.....

Before this case receives the consideration of the Committee the Surveyors should, in view of their reporting bolted patches as a war emergency measure, be requested to furnish their recommendations regarding permanent repairs.

*Handwritten:* May 24.3.41



© 2020

Lloyd's Register  
Foundation

W383-0180

*in our opinion to remain as now classed with fresh record*