

Shipbuilders.

AIR RECEIVERS NO

AIR RECEIVER Endorsement. Messrs Shorts Potts. YARDN<sup>OS</sup> 460, 463. # K1020/1 - K1022/3.

Burntisland S.B.Co. YARDN<sup>E</sup> 230 - K1034/5

Messrs Daxford & Sons LTD. Yard N<sup>OS</sup> 664, 660, 668, 658, 659 -

~~Shipbuilders~~:- AIR RECV<sup>RS</sup> N<sup>OS</sup> K1036/7 | K1044/5 | K1040/1 | K1042/3 No.

Makers:- Cochran & Co (Amen) LTD. K1052/3 Air Receiver No.

It is submitted that the plan of Rusted starting  
air receivers merits approval for a working pressure of 600 lb.  
per sq. ins, provided the air receivers be constructed under  
the usual conditions of survey and testing.

Return plan. 8  
Retain copy. 8

*L 28/9*

*[Signature]*

*J. W. H.*  
21.9.39.

K39-0276

