

4 MAR 1948

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "GALAXIAS".

Rpt. C&f.

No. 53297

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to damaged stem and stem plating being dealt with at the Owners' convenience.

Action has been deferred for examination in drydock after grounding.

The Cardiff Surveyors now report the vessel placed in drydock, the bottom coated, and on account of damage through grounding, some fractured shell plating at bulkhead brackets, and some fractures in deck plates at the aft end of the Donkey Boiler casing repaired, and minor repairs carried out.

The stem and stem plating, as above, continue efficient.

It is submitted the vessel appears worthy to remain as classed with record of survey 2-40, subject as above.

100AI.

Shelter deck with freeboard } Subject, etc.

2-40 C&f.

S.R.L. Delete: Dry Docking (grounding)

W398-0186

26.2.48

Lloyd's Register Foundation

RETAIN

RETAIN



© 2020

Lloyd's Register
Foundation

(Period
com
exte
sho
sum
sho
resp

In dan
off

REPA

ab
(
M

SUMMA

F
F
F

PRESEN

Dacks ...

Caulking

Coaming

Beams &

Outside

"

Breastho

Transom

Frames

Reverse

Longitud

Transver

Floors ...

Keelsons

Stringer

Inner Bo

Gen