

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

30th October 1939.

Dear Sirs,


S/S Galaxias

M With reference to the call at this Office of your Representative, Mr. Dutton, I have to acquaint you that the question of the fitting of the doubling to the stringer plate in this vessel has been discussed with him. He explained that it would be very difficult to fit this doubling in way of the side house amidships, and it was arranged that the doubling would be fitted as required beyond the side house and that, in way of this house, the strake adjacent to the house would be doubled with a plate having the same sectional area, and this doubling would overlap the stringer doubling about 2 frame spaces at each end.

I am, Dear Sirs,
Yours faithfully,

Secretary.

Messrs. Lyras & Lemos Bros. Ltd.,
9, Camomile Street,
LONDON, E.C.3.



© 2020

Lloyd's Register
Foundation

W 398 - 0201