

Lloyd's Register of Shipping,

WATERPORT,
18, Cornwall's Lane,

LLOYD'S REGISTER
RECEIVED
25 APR 1927
And
The Secretary,
LONDON

Gibraltar, April 20th, 1927.

Lloyd's Register of Shipping,
71, Fenchurch Street,
London. E. C. 3

Dear Sir,

I enclose translation and confirmation of my telegram today re S.S."GANDARA".

The Owner's Superintendent is unable to get any drawings either from the Builders or B.I. Co's Head Office, and as the vessel's form has been destroyed up to about the 16 ft: draught mark at the stem, with the stem and deep floors all torn away to the collision bulkhead, also from that point aft to No. 1/2 bulkhead the bottom and keel plates are badly set up, it would greatly assist us in rebuilding if we could get some offsets of the different frame stations over this distance.

If you are unable to send these drawings the Drawing Office Dockyard Chief Constructor's Dept. will put the work in hand as soon as the wreckage is burnt off and cleared away.

I am, Dear Sir,

Yours faithfully

W. J. Matthews
W. J. MATTHEWS.

W40-0074

© 2019
Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

25 APR 1951
Also for Mr. S. A. Hill to note.
Yours faithfully
John T. M. Watt



© 2019

Lloyd's Register
Foundation