

# BARTRAM & SONS LIMITED

Shipbuilders



Since 1837

PLEASE QUOTE:  
YOUR REF.

RLN:VB.

SOUTH DOCK

SUNDERLAND

28th April, 1939.

(Friday.)

Messrs. Lloyd's Register of Shipping,  
Fawcett Street,  
SUNDERLAND.

Dear Sirs,

Re: s.s. Nos. 282/283.

Referring to the Midship section approved by your Committee for above vessels, the Upper Stringer plate was approved 72" x .64" and the Second Deck Stringer Plate 83" x .40". The plan of Multiple Punch Rivetting submitted with our letter of the 24th instant shows the Upper Deck Stringer 63.3/4" and the Second Deck 81.1/2" wide. In view of the reduced widths we propose to make the former .65" thick retaining the thickness of .40" in the latter.


If this modification does not meet with your approval, we shall be glad if you will telephone us as early as possible to-morrow.

Yours faithfully,

FOR AND ON BEHALF OF  
BARTRAM and SONS LTD.

Forward D. Pickering 11/5/39

that above alterations are in order  
but upper stringer plate about  
known section should be increased  
from .81 to .85.



Lloyd's Register  
Foundation

W43-0064