

11 OCT 1939 1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME NEWTON BEECH Rpt. C. Tn. No. 2488

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor DAMAGE.

Damage through Heavy Weather.

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

A number of bottom ribs renewed forward & minor repairs effected.


Vessel placed in dry dock

It is submitted the vessel is worthy to remain as classed with

record of Survey 9.39

100A1.

9.39 C. Tn.



© 2020

Lloyd's Register
Foundation

W431-0127