

for damage stated to have been sustained through collision

17 NOV 194 E

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

"USK MOUTH".

Rpt.

Lth.

No.

19964.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also, to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Auxiliary condenser discharge pipe(cracked) renewed.

It is submitted the vessel is eligible to remain

as classed without fresh record.



© 2021

17.11.39.

Lloyd's Register  
Foundation

W445-0139

Subject to Lloyd's Register.

now classed without fresh