

REPORT on the

S.S. "Joyce Cleveland"


It is concluded that the nut and screw bolts for securing the
otted plates at the openings in the Bridge front pass through the
aluminum plating but the surveyor should confirm this.

Yes

W.H.

S.S.
15.4.24

W449-0055



© 2020

Lloyd's Register
Foundation