

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

ENCLOSURES.

29th January, 1937.

Dear Sirs,

I return herewith the plans forwarded with your letter of the 28th instant regarding the bulb angle stiffeners on the hatch coamings in respect of Messrs. George Brown & Co., Ltd's Yard No. 201, and in reply have to inform you that the Regulations, Rule 16, require the stiffener to be placed "not lower than 10" below the upper edge" of the coaming, and it is considered that this Rule should be complied with.

I am, Dear Sirs,


Yours faithfully,

copy Gls.

pro Secretary.

The Surveyors,

GREENOCK.



© 2020

Lloyd's Register
Foundation

W449-0362